Phase II Stacked Mezzanine Cards – Temperature Stress Test





First 630 cards in the climate cabinet

Scanning Program

4 Ramp-Ups:

- 20-60-20
- check for bad soldering
- monitoring done by digitemp sensors (uncalibrated → sanity check)
- empty cabinet → 12.5h/630 cards



